

# TruVision IP PTZ Camera Firmware V5.2.e Release Notes

P/N 1005-EN • REV B • ISS 12MAY23

## Introduction

This is the TruVision IP PTZ Camera Firmware V5.2.e Release Notes with additional information not covered in the user manual. For the latest information on the TruVision IP PTZ cameras, please visit:

EMEA: [www.firesecurityproducts.com](http://www.firesecurityproducts.com)

Australia: [www.interlogix.com.au](http://www.interlogix.com.au)

## Supported camera list

| <b>PAL versions</b> | <b>NTSC versions</b> |
|---------------------|----------------------|
| TVP-1101            | TVP-3101             |
| TVP-1102            | TVP-3102             |
| TVP-1103            | TVP-3103             |
| TVP-1104            | TVP-3104             |
| TVP-1105            | TVP-3105             |
| TVP-1106            | TVP-3106             |
| TVP-1107            | TVP-3107             |
| TVP-1122            | TVP-3122             |

## Improvements with Firmware V5.2.e (May 2023)

- Security updates

## Improvements with Firmware V5.2.d

- Improvements to return to the initial position after PTZ auto-tracking

- Alarm host field added in the menu Configuration>Network>Port
- ISAPI modifications

## Contacting Support

For help installing, operating, maintaining, and troubleshooting this product, refer to this document and any other documentation provided. If you still have questions, contact us during business hours (Monday through Friday, excluding holidays).

**Note:** Please be ready at the equipment before calling.

---

### Europe, Middle East, and Africa

---

W Go to [www.firesecurityproducts.com/en/contact](http://www.firesecurityproducts.com/en/contact)

---

### Australia

---

E [cs@firesecurityproducts.zendesk.com](mailto:cs@firesecurityproducts.zendesk.com)

---

W [www.firesecurityproducts.com.au/support](http://www.firesecurityproducts.com.au/support)

---